

STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

7272 Cleanwater Lane • PO Box 47775 • Olympia, Washington 98504-7775 • (206) 753-2353

January 31, 1994

Ms. Karen Keeley
U.S. Environmental Protection Agency
Region 10
1200 6th Avenue, HW-113
Seattle, Washington 98101-3188

Re: Final Milestone 1 Source Control Status Report for Middle Waterway

Problem Area: Commencement Bay Nearshore/Tideflats Superfund Site

Dear Ms. Keeley:

I have enclosed the final Milestone 1 Report for the Middle Waterway Problem Area at the Commencement Bay Nearshore/Tideflats (CBN/T) Superfund Site. The report contains a table that identifies all ongoing potential sources of problem chemicals (List 1), all probable sources (List 2), and all confirmed sources (List 3). All lists are included on the same table. In addition, List 3 sites are printed separately (last page). A map is also enclosed with numbered locations or symbols for each site.

In deciding how to list facilities, Ecology used the source identification process described in the EPA document titled: "Source Control Strategy: Commencement Bay Nearshore/Tideflats Superfund Site (May, 1992)." The listing process was designed to determine which sites located on Middle Waterway are ongoing sources of problem chemicals. The problem chemicals used were those identified on an attached table. "Problem chemicals" are those which have been found in Middle Waterway sediments above levels considered harmful to biota and human health and are listed in EPA's Record of Decision for the Commencement Bay Nearshore/Tideflats Superfund site.

List 1 includes: (1) all properties directly adjacent to Middle Waterway, (2) all properties draining to Middle Waterway with owners or operators who were issued a General Notice Letter by EPA, and (3) other properties that drain to Middle Waterway, including some that drain to a municipal storm drain (MI-200 is the only municipal drain that discharges to Middle Waterway). This report also lists MI-200 separately as a potential source.

List 2 excludes some List 1 sites based on information obtained from file searches and site visits.

USEPA SF

1016624

Karen Keeley January 31, 1994 Page 2

List 3 sites are confirmed sources based on analyses of samples for contaminants in soil, sediment, ground water, or surface water. Sources listed as "major sources" in the EPA Record of Decision are identified.

Properties may be removed from List 3 if investigations performed by the facilities convince Ecology that they do not contribute problem chemicals to the waterway. In addition, facilities may be added to List 3 based on new information.

Ecology identified 31 potential sources for List 1, 15 probable sources for List 2, and 8 confirmed sources for List 3.

Also enclosed in this Milestone 1 Status Report are the following maps:


- (1) Locations of each property, facility, and municipal storm drain outfall shown on List 1.
- (2) A copy of the Tacoma-Pierce County Health Department Storm Water Drainage map for Middle Waterway, updated as of June 1993.

Sincerely,

Dave Smith Unit Supervisor

Southwest Regional Office Toxics Cleanup Program


DS:ak



Commencement Bay Nearshore/Tideflats Middle Waterway Source Control Status Report: Milestone 1

Washington Department of Ecology Toxics Cleanup - SWRO Urban Bay Action Team

January 1994





PROBLEM CHEMICALS IN MIDDLE WATERWAY

Priority ^a	Chemical
Priority 1	
Priority 2	Copper
	Mercury
Priority 3	Arsenic
	Zinc
	Lead
·	. LPAH
	HPAH
	Diterpenoid hydrocarbons ^{b,c}
	Dibenzothiophene ^{b,c}
	4-Methylphenol ^b
	Methylpyrenes ^{b,c}
	Dichlorobenzenes
	Phenol
	Pentachlorophenol

Priority 1 problem chemical—Detected at concentrations exceeding apparent effects thresholds, and the spatial distribution of this chemical corresponds to gradients of observed toxicity or benthic effects.

Priority 2 problem chemical—Detected at concentrations exceeding apparent effects thresholds at more than one station, but shows no particular spatial relationship with gradients of observed toxicity or benthic effects.

Priority 3 problem chemical—Detected at concentrations exceeding apparent effects thresholds at only one station in a problem area or is the highest recorded concentration of that chemical in the Puget Sound database.

^b The Record of Decision does not include a CB/NT cleanup objective for this constituent.

^c Additional information on these tentatively identified compounds is discussed on pp. 138–145 of Tetra Tech (1986b).

	: List 1	:	List 2	:	List 3	: Reason Site is Not on List 3	: Comments/Notes
No.	: (Potential Sources)	:	(Probable	:	(Confirmed	:	:
	:	:	Sources)	:	Sources)	:	:
1	: BP Oil (part that is on "F" St)	:		:		: Site engineered to drain to Mouth of Thea	:
	: See map	:		:		: Foss Waterway. Contaminated groundwater	:
	: Tacoma	:		:		: drains to Mouth of Thea Foss (part of	:
	:	:		:		: ongoing "D" Street cleanup).	:
•	: Brass Foundry Slag	:	x	:	×	:	: Simpson will move contamination away from the
	: See map	:	•	:		:	: bank and dispose off-site or isolate from
	: Tacoma	:		:		:	: precipitation under a clay cap. The work will
	:	:		:		:	: be performed as part of a larger shore restoration project.
	: Capital Material Handling	:	•	:		: Does not drain to Middle Waterway. Site is	; :
	: 435 E. 11th	:		:		: engineered to route surface runoff to Mouth	· •
	: Tacoma	:		:		: of Thea Foss Waterway.	:
	:	:		:		:	:
1	: City of Tacoma (Vacant Property)	:		:		: Existing information suggests that this	:
٠	: See map	:		:		: property does not contribute problem	:
	: Tacoma	:		;	•	: chemicals to the waterway. Not sampled.	:
	: 	:		:		:	:
◀	: City of Tacoma Storm Drain MI-200	:	х	:		: Problem chemicals identified. Existing	:
	: See map	:	1	:		: information suggests that an enforcement	:
:	: Tacoma	:		:		: action for source control is not necessary	:
	•	:		:		: at this time. Sampled.	:

•	: List 1 : (Potential Sources)	:	(Probable	:	List 3 (Confirmed Sources)	,	: Comments/Notes :
4B	: Coast Craft Cabinets Warehouse		X	_	x	•	: Cleanout of catch basins and storm drain line
40	: 1002 East "F" Street	:	^	:	^	•	: needed. "E" Street side of Coast Craft
	: Tacoma	•	•	:		•	: Cabinets (4A) drains to the Mouth of Thea Fos
	:	:		:		:	: Waterway.
	·						
3	: Coast Crane Company	:		:		: Existing information suggests that this	: Truck storage yard only.
	: 501 East "F" Street	:		:		: facility does not contribute problem	:
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:
	:	:		:		:	:
 E	: Cooks Marine Specialties					- No lease in exercise - Con Food Marieira	. Description of the second
,	: 223 East "F" Street					: No longer in operation. See Foss Maritime.	: Previously listed as a major source.
	: Tacoma	•		•			
	. racona	•		•			
	•	•		•		•	
7	: F Street Partners	:	x	:		: Existing information suggests that this	: Bank contamination addressed separately under
•	: Vacant property. See map.	:	:	:	•	: property does not contribute problem	: "Steel Foundry Slag".
	: Tacoma	:		:		: chemicals to the waterway.	:
	:	:		:		:	:
6	: Foss Maritime	:	x	:	x	:	: Metal turnings under the old Cook's Marine
	: 225 East "F" Street	:		:		:	: dock (intertidal) need to be removed or teste
	: Tacoma	:		:		:	: to ensure no toxic metals are present.
	:	:		:		:	:
8	: Gerrish Bearing	:		:	• • • • • • • • • • • • • • • • • • • •	: Existing information suggests that this	:
	: 1011 East "E" Street	:		:		: facility does not contribute problem	:
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:
	:	•		:		:	•

•	: List 1 : (Potential Sources)	:	•	:	List 3 (Confirmed Sources)	·	: Comments/Notes :
9	: Jack Carlyle Trucking	:	×	:	x	:	: Ecology will work with the tenant (Jack
	: 639 East "F" Street	:		:		:	: Carlyle) and land owner (Foss Maritime) to
	: Tacoma	:		:	•	:	: clean out catch basins.
	:	:		:		:	:
10	: Lyden Castparts	:		:	`	: Existing information suggests that this	:
	: 653 East 11th	:		:		: facility does not contribute problem	•
	: Tacoma	:		:	•	: chemicals to the waterway. Not sampled.	:
	:	:		:		•	:
11	: Marine Industries NW	:	x	:	х	······	: Major source. Has an individual NPDES permit.
	: 313 East "F" Street	:		:		:	: Implementation of permit ongoing.
	: Tacoma	:		:		:	:
	:	:		:		:	:
12	: Matheus Lumber	:		:		: Existing information suggests that this	:
	: 733 East 11th Street	:		:		: facility does not contribute problem	:
	: Tacoma	:	•	:		: chemicals to the waterway. Not sampled.	:
	:	:		:		:	:
13	: McMillan Bloedel	:		:		: Existing information suggests that this	:
	: 733 East 11th Street	:		:		: facility does not contribute problem	:
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:
	:	:		:		:	:
14	: Morse Industrial Supply	:		:		: Existing information suggests that this	:
	: 711 East 11th Street	:		:		: facility does not contribute problem	:
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:
	:	:		:		:	:

•	: List 1 : (Potential Sources) :		: List 3 ple : (Confirmed ps) : Sources)	: Reason Site is Not on List 3 :	: Comments/Notes :
15	: Nicholson Engineering	:	:	: Existing information suggests that this	:
	: 680 East 11th St.	:	:	: facility does not contribute problem	:
	: Tacoma	:	:	: chemicals to the waterway. Not sampled.	:
	:	:	:	:	:
28	: Norcore Plastics	: 6	:	: Existing information suggests that this	: Formerly Vlahovich Boats.
	: 733 East 11th Street	:	:	: facility does not contribute problem	:
	: Tacoma	:	:	: chemicals to the waterway. Not sampled.	:
	:	:	:	:	:
23	: Office Building	:	:	: Existing information suggests that this	:
	: 733 East 11th Street	:	:	: facility does not contribute problem	:
	: Tacoma	:	:	: chemicals to the waterway. Not sampled.	:
	:	•	:	:	:
16	: Pacific Yacht Basin	: x	:	: Existing information suggests that this	: Need to reinspect periodically for cleanout of
	: 609 East 11th Street	:	:	: facility does not contribute problem	: oil-water separator. Also see "Sandblast Grit
	: Tacoma	:	:	: chemicals to the waterway. Not sampled.	: on Bank, Head of WW".
	:	:	:	:	:
17	: Paxport Mills	: x	:	: Existing information suggests that this	:
	: 300 Middle Waterway	:	:	: facility does not contribute problem	:
	: Tacoma	:	:	: chemicals to the waterway. Not sampled.	:
	:	:	:	:	:
18	: Pioneer Painting	: x	: x	:	: Work done at Marine Industries NW addressed
	: 255 East "F" Street	:	:	:	: under MINW's NPDES permit. Potential sandblast
	: Tacoma	:	:	:	: grit cleanup addressed separately.
	•	:	:	:	:

Map	: List 1	:	List 2	:	List 3	: Reason Site is Not on List 3	: Comments/Notes
No.	: (Potential Sources)	:	(Probable	: (Confirmed	:	:
	:	:	Sources)	:	Sources)	:	•
19	: Puget Sound Plywood	:		:	_	: Does not drain to Middle Waterway. Drains	:
	: 230 East "F" Street	:		:		: to Mouth of Thea Foss Waterway.	:
	: Tacoma	:		:		:	:
	•	:		. :			:
16	: Sandblast Grit on Bank, Head of WW	:	, x	:	×	:	: Ecology is discussing options with potentially
	: Near Pacific Yacht Basin	:		:		:	: responsible parties.
	: Tacoma	:		:		:	:
	:	:		:		:	:
20	: Sea Wall Construction	:	. X	:		: Existing information suggests that this	: Some BMP improvements were implemented.
	: Green Bldg on "F" St.	:		:		: facility does not contribute problem	: Ecology will monitor site to ensure small are
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	: of oil-soaked soil is removed.
	:	:		:		:	
21	: Shell Oil (part that is on "F" St)	:		:		: Site is engineered to drain to Mouth of	:
	: See map	:		:		: Thea Foss Waterway. Contaminated	:
	: Tacoma	:		:		: groundwater drains to Mouth of Thea Foss	:
	:	:		:		: (part of "D" Street cleanup).	:
2	: Simpson Tacoma Kraft on Middle	:	. x	:		: Problem chemicals identified. Existing	: Simpson Tacoma Kraft is planning habitat
	: See map; vacant property	:		:		: information suggests that an enforcement	: restoration work on this property. Also see
	: Tacoma	:		:	•	: action for source control is not necessary	: "Brass Foundry Slag".
	:	:		:		: at this time. Sampled.	:
•	: Steel Foundry Slag	:	, x	:	· x	:	: Ecology is discussing options for addressing
	: See map	:		:		:	: bank contamination with potentially
	: Tacoma	:		:		:	: responsible parties.
	:	:	•	:		•	:

Map	: List 1	:	List 2	:	List 3	: Reason Site is Not on List 3	:	Comments/Notes
No.	: (Potential Sources)	:	(Probable	:	(Confirmed	•	:	
		:	Sources)	:	Sources)	:	:	
	: Tacoma City Light	:		:		: Existing information suggests that this	:	***
	: 1013 East "F" Street	:		:		: facility does not contribute problem	:	
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:	
	:	:	· · · · · ·	:		:	:	
25	: Tacoma Fire Department	:		:		: Existing information suggests that this	:	
	: 1015 East "F" Street	:		:		: facility does not contribute problem	:	
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:	
	:	:		:		:	:	
26	: Texaco (Ronaco, Inc.)	:		:		: Existing information suggests that this	:	
	: 801 East 11th	:		:		: facility does not contribute problem	:	
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:	
	:	:		:		:	:	
 27	: The Truss Company	:		:		: Existing information suggests that this	:	
•	: 733 East 11th Street	:		:		: facility does not contribute problem	:	
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:	
	:	:		:		:	:	
17	: Union Pacific Railroad Co.	:		:		: Existing information suggests that this	: R	Railway line.
	: W. side of Middle W. St.	:		:		: property does not contribute problem	:	
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:	
	:	:.		:		•	:	
29	: Washington Belt & Drive Systems	:		:		: Existing information suggests that this	:	
	: 672 East 11th Street	:		:		: facility does not contribute problem	:	
	: Tacoma	:		:		: chemicals to the waterway. Not sampled.	:	-
	:	:		:		•	:	

Page 7 1/31/94

MIDDLE WATERWAY PROBLEM AREA COMMENCEMENT BAY NEARSHORE/TIDEFLATS SUPERFUND SITE Potential, Probable, and Confirmed Sources(a)

Map : List 1	:	List 2	: List 3	: Reason Site is Not on List 3	: Comments/Notes
No. : (Potential Sources)	:	(Probable	: (Confirmed	: '	:
:	:	Sources)	: Sources)	:	:
30 : Western Machine Works	:	x	:	: Existing information suggests that this	: Oily soils were cleaned up and improper waste
: 666 East 11th Street	:		:	: facility does not contribute problem	: management practices were corrected.
: Tacoma	:		:	: chemicals to the waterway. Not sampled.	:
:	:		:	:	:

FOOTNOTES

(a) Potential sources (List 1) were considered to be all sites with drainage to Middle Waterway.

Sites were put on List 2 after inspections revealed they were probable sources of problem chemicals to Middle Waterway.

Sites were put on List 3 after sampling or further investigation showed that the site was an ongoing confirmed source of problem chemicals to
Middle Waterway. Documentation why sites were not placed on List 3 is briefly described in the fifth column of this report. More specific information about sites
placed on List 3 is found in a separate attached table titled: "List 3 - Confirmed Sources". Further detail is provided in Ecology's site files, inspection reports,
and in a Middle Waterway Problem Area inspection notebook maintained by the Ecology UBAT supervisor at the Southwest Regional Office.

MIDDLE WATERWAY PROBLEM AREA COMMENCEMENT BAY NEARSHORE/TIDEFLATS SUPERFUND SITE

List 3 - Confirmed Sources (a)

Page 1

1/31/94

lap :		:	:		:	
lo.	: Site Name	: Status	:	Contaminants (b)	:	Pathways
• :	: Brass Foundry Slag	: Simpson will address contamination as part of a	:	As, Cu, Pb, Zn	:	Direct
:	:	: larger shore restoration project.	:	·	:	
:	:	:	:		:	
3 :	Coast Craft Cabinets Warehouse	: Owner has been contacted regarding a drain	:	Pentachlorophenol,	:	Storm water
:	•	: cleanout this spring.	:	HPAH's	:	
:	1	:	:		:	
:	Foss Maritime	: Metal turnings under the old Cook's Marine dock	:	Metals	:	Direct
:		: (intertidal) need to be removed or tested to	:		:	
:		: ensure there are no toxic metals.	:		:	
:	Jack Carlyle Trucking	: Ecology will work with tentant (Jack Carlyle)	 :	As, Cu, Pb, Zn	· · · ·	Storm water
:		: and land owner (Foss Maritime) to clean out	:		:	
:		: catch basins.	:		:	
 I ;	Marine Industries NW	: Major source. Has an individual NPDES permit.	:	As, Cu, Pb, Zn, Hg	·	Storm water, ground water,
:		: Implementation of permit is ongoing.	:		:	direct
:		:	:		:	
B :	Pioneer Painting	: Work done at Marine Ind NW is addressed in the	:	As, Cu, Pb, Zn	:	Ground water, storm water
:		: MINW NPDES permit. Grit cleanup at Pioneer will	:		:	
:	•	: be handled separately.	:		:	
:	Sandblast Grit on Bank, Head of WW	: Will meet with EPA to discuss strategy on	:	As, Cu, Cd, Zn	:	Storm water, direct
:		: addressing bank contamination.	:		:	
:		:	:		:	
 -:	Steel Foundry Slag	: Will meet with EPA to discuss strategy on	:	As, Cu, Pb, Zn, HPAH's	:	Direct
:		: addressing bank contamination.	:	· ·	:	
	•	•				

MIDDLE WATERWAY PROBLEM AREA COMMENCEMENT BAY NEARSHORE/TIDEFLATS SUPERFUND SITE

1/31/94

List 3 - Confirmed Sources (a)

(a)	Sites were put on List 3 after sampling or further investigation of probable sources showed that the site was an
	ongoing confirmed source of problem chemicals to Middle Waterway. Additional detail is provided in Ecology's site files, inspection
	reports, and in a Middle Waterway Problem Area inspection notebook maintained by the Ecology UBAT supervisor at the Southwest Regional Office.

(b) Additional problem chemicals or pathways may be present at sites.